

### Style A - MODELS AND DIMENSIONS

Model	C.F.M Air Flow	EXT S.P. in W.G.	H.P. Motor	A	B	C	D	E	F	G	H	Weight Lbs.
MS-004	400	3 1/2"	1 1/2	1'-3"	1'-3"	1'-0"	1'-10"	1'-9"	4 1/2"	3"	5'-6"	350
MS-005	500	4 1/2"	2	1'-6"	1'-6"	1'-3"	1'-10"	1'-9"	5 3/8"	3"	5'-7"	410
MS-006	600	5"	3	1'-6"	1'-8"	1'-3"	1'-10"	1'-9"	5"	4"	6'-0"	410
MS-007	700	5"	3	2'-0"	2'-0"	1'-3"	1'-10"	1'-9"	5 3/8"	4"	6'-6"	480
MS-008	800	5"	5	2'-0"	2'-0"	1'-3"	1'-10"	1'-9"	6 3/8"	4"	6'-6"	520
MS-009	900	5"	5	2'-0"	2'-0"	1'-3"	1'-10"	1'-9"	7 1/4"	4"	6'-6"	530
MS-010	1000	5"	5	2'-0"	2'-0"	1'-3"	1'-10"	1'-9"	6 1/2"	4"	6'-6"	540
MS-015	1500	5"	7 1/2	2'-0"	2'-0"	1'-6"	2'-3"	2'-2"	8"	5"	7'-9"	590
MS-020	2000	5"	7 1/2	2'-9"	3'-0"	1'-6"	2'-3"	2'-2"	9 1/8"	6"	9'-10"	950
MS-025	2500	5"	10	3'-0"	3'-6"	1'-9"	2'-3"	2'-2"	10"	7"	10'-0"	1000
MS-030	3000	5"	15	3'-6"	3'-6"	1'-9"	2'-3"	2'-2"	10 5/8"	8"	10'-0"	1030
MS-035	3500	5"	15	4'-0"	3'-6"	2'-0"	2'-3"	2'-2"	12 1/2"	9"	10'-5"	1100
MS-040	4000	5"	20	4'-0"	4'-0"	2'-0"	2'-10"	2'-9"	11 5/8"	9"	10'-7"	1500
MS-050	5000	5 1/2"	20	5'-0"	4'-0"	2'-0"	2'-10"	2'-9"	13 3/8"	11"	11'-0"	1700
MS-060	6000	5 1/2"	25	6'-0"	4'-0"	2'-0"	2'-10"	2'-9"	16"	12"	11'-8"	1950
MS-070	7000	5"	25	7'-0"	4'-0"	2'-0"	2'-10"	2'-9"	18 3/4"	12"	11'-6"	2800
MS-080	8000	5"	2 X 15	8'-0"	4'-0"	2'-0"	2'-10"	2'-9"	18 3/4"	12"	11'-6"	3100
MS-090	9000	5 1/2"	2 X 20	9'-0"	4'-0"	2'-0"	2'-10"	2'-9"	19 1/4"	14"	11'-6"	3800
MS-100	10000	5 1/2"	2 X 20	10'-0"	4'-0"	2'-0"	2'-10"	2'-9"	21"	15"	11'-8"	4200
MS-110	11000	5 1/2"	2 X 25	11'-0"	4'-0"	2'-0"	2'-10"	2'-9"	22"	16"	12'-3"	4800
MS-120	12000	5 1/2"	2 X 25	12'-0"	4'-0"	2'-0"	2'-10"	2'-9"	24"	16"	12'-6"	5800

### Style B - MODELS AND DIMENSIONS

Model	C.F.M Air Flow	EXT S.P. in W.G.	H.P. Motor	A	B	C	D	E	F	G	H	Weight Lbs.
MS-004	400	3 1/2"	1 1/2	1'-3"	1'-3"	3'-0"	1'-0"	3"	4 1/2"	6'-10"	1 1/2"	430
MS-005	500	4 1/2"	2	1'-6"	1'-6"	3'-4"	1'-0"	3"	5 3/8"	7'-2"	1 1/2"	470
MS-006	600	5"	3	1'-6"	1'-8"	3'-4"	1'-0"	4"	5"	7'-9"	1 1/2"	490
MS-007	700	5"	3	2'-0"	2'-0"	4'-7"	1'-0"	4"	5 3/8"	7'-9"	1 1/2"	530
MS-008	800	5"	5	2'-0"	2'-0"	4'-7"	1'-0"	4"	6 3/8"	7'-9"	1 1/2"	570
MS-009	900	5"	5	2'-0"	2'-0"	4'-7"	1'-0"	4"	7 1/4"	7'-9"	1 1/2"	590
MS-010	1000	5"	5	2'-0"	2'-0"	4'-7"	1'-0"	5"	6 1/2"	7'-9"	1 1/2"	600
MS-015	1500	5"	7 1/2	2'-0"	2'-0"	4'-9"	1'-3"	6"	8"	10'-5"	1 1/2"	630
MS-020	2000	5"	7 1/2	2'-9"	3'-0"	4'-9"	1'-3"	7"	9 1/8"	12'-5"	1 1/2"	990
MS-025	2500	5"	10	3'-0"	3'-6"	5'-4"	1'-3"	8"	10"	13'-2"	1 1/2"	1090
MS-030	3000	5"	15	3'-6"	3'-6"	5'-10"	1'-3"	9"	10 5/8"	13'-2"	1 1/2"	1130
MS-035	3500	5"	15	4'-0"	3'-6"	5'-10"	1'-3"	9"	12 1/2"	14'-0"	1 1/2"	1200
MS-040	4000	5"	20	4'-0"	4'-0"	5'-10"	1'-3"	11"	11 5/8"	13'-8"	2"	1600
MS-050	5000	5 1/2"	20	5'-0"	4'-0"	7'-10"	1'-3"	12"	13 3/8"	15'-0"	2"	1800
MS-060	6000	5 1/2"	25	6'-0"	4'-0"	6'-0"	1'-3"	12"	16"	14'-11"	1 1/2"	2050
MS-070	7000	5"	25	7'-0"	4'-0"	6'-0"	1'-4"	12"	18 3/4"	14'-9"	1 1/2"	2920
MS-080	8000	5"	2 X 15	8'-0"	4'-0"	6'-0"	1'-4"	14"	18 3/4"	14'-9"	1 1/2"	3250
MS-090	9000	5 1/2"	2 X 20	9'-0"	4'-0"	6'-4"	1'-4"	15"	19 1/4"	15'-1"	1 1/2"	3980
MS-100	10000	5 1/2"	2 X 20	10'-0"	4'-0"	6'-10"	1'-4"	16"	21"	15'-9"	2"	4400
MS-110	11000	5 1/2"	2 X 25	11'-0"	4'-0"	7'-4"	1'-4"	16"	22"	16'-10"	2"	5200
MS-120	12000	5 1/2"	2 X 25	12'-0"	4'-0"	7'-8"	1'-4"	16"	24"	17'-5"	2"	6200